Dynasty 210 DX (MIL907686)

MIL907686 Dynasty 210 DX Miller TIG Machine

- Electrical Requirements:
 - o 110/115/120; 208; 220/230/240; 380/400, 460/480V
 - o 1 and 3-phase
 - o 50/60 Hz
- Processes: AC/DC GTAW, SMAW, GTAW-P

8' Primary Cord

Adjustable Shoulder Strap

(2) 50 mm Dinse Style Connectors

Dynasty 210 DX Runner Package (MIL951668)

- Electrical Requirements:
 - o 110/115/120; 208; 220/230/240; 380/400, 460/480V
 - o 1 and 3-phase
 - o 50/60 Hz
- Processes: AC/DC GTAW, SMAW, GTAW-P, CAC-A, Aluminum

Coolmate 1.3 Coolant System

Small Runner Cart

Weldcraft W-250 Torch Kit & Accessories 300185

- W-250, W-250 Valve
- Smith Argon Flowmeter/Regulator w/ Hose
- 12' Ground Cable and Clamp, Work Lead w/ Clamp, Dinse Connector
- AK4C Torch Accessory Kit (Shielding Cups Collets, Collet Bodies, Tungsten)
- Water Cooled Dinse Torch Adapter
- Extra Consumables in Welding Accessory Kit

(4) 1-gal Coolant

RFCS-14HD Foot Control & Receiver 194744

• AK3C Torch Accessory Kit (2) Chains to Secure Gas Cylinders

Input Power: 240 V, Single-Phase	
Proces	ses:
•	MIG (GMAW)
•	Flux-Cored (FCAW)
•	DC Stick (SMAW)
•	DC Lift-Arc TIG (GTAW)
•	Pulsed TIG (GTAW-P)
Auto-S	et Elite (Pre-Defined Weld Settings)
•	MIG
•	Stick
•	DC Lift-Arc TIG
Auto-0	Gun Detect
Packa	ge Components:
7' I	ndustrial Power Cord
15'	250-amp MDX-250 MIG Gun w/ Accu-Lock MDX Consumables
	 Nozzle, (10) Contact Tips, Diffuser, Insulator, Storage Box
10′	Cable w/ Electrode Holder & 50 mm Dinse-Style Connector
10′	Work Cable w/ Clamp & 50 mm Dinse-Style Connector
(2)	Flow Gauge Regulators & Gas Hoses for Argon or AR/CO₂ Mix
	Flow Gauge Regulators & Gas Hoses for Argon or AR/CO ₂ Mix 0/.035" Reversible Drive Rolls
.03	
.03 Ext	0/.035" Reversible Drive Rolls
.03 Ext	0/.035" Reversible Drive Rolls ra Contact Tips
.03 Ext Ma	0/.035" Reversible Drive Rolls ra Contact Tips terial Thickness Gauge
.03 Ext Ma	0/.035" Reversible Drive Rolls ra Contact Tips terial Thickness Gauge Latch Dual Cylinder Running Gear w/ Elevated Gun & Cable Rack